



File E125172

Vol 1

Auth. Page 1

Issued: 1989-07-27
Revised: 2018-01-09

FOLLOW-UP SERVICE PROCEDURE
(TYPE R)

UNLISTED COMPONENT

SYSTEMS, ELECTRICAL INSULATION
(OBJY3)

Manufacturer: SEE ADDENDUM FOR MANUFACTURER LOCATIONS

578493 (Party Site)
Applicant: WARNER ELECTRIC INC
(142909-001) 449 GARDNER ST
SOUTH BELOIT IL 61080-1326

This Follow-Up Service Procedure authorizes the above Manufacturer(s) to use the marking specified by UL LLC, or any authorized licensee of UL LLC, including the UL Contracting Party, only on products when constructed, tested and found to be in compliance with the requirements of this Follow-Up Service Procedure and in accordance with the terms of the applicable service agreement with UL Contracting Party and any applicable Service Terms. The UL Contracting Party for Follow-Up Services is listed on addendum to this Follow-Up Service Procedure ("UL Contracting Party"). UL Contracting Party and UL LLC are referred to jointly herein as "UL."

UL further defines responsibilities, duties and requirements for both Manufacturers and UL representatives in the document titled, "UL Mark Surveillance Requirements" that can be located at the following web-site: <http://www.ul.com/fus> and in the document titled "UL and Subscriber Responsibilities" that can be located at the following website: <http://www.ul.com/responsibilities>. Manufacturers without Internet access may obtain the current version of these documents from their local UL customer service representative or UL field representative. For assistance, or to obtain a paper copy of these documents or the applicable Service Terms, please contact UL's Customer Service at <http://ul.com/aboutul/locations/>, select a location and enter your request, or call the number listed for that location.

The Applicant and the specified Manufacturer(s) in this Follow-Up Service Procedure must agree to receive Follow-Up Services from UL Contracting Party. If your applicable agreement is a Global Services Agreement ("GSA") with an effective date of January 1, 2012 or later and this Follow-Up Service Procedure is issued on or after that effective date, the Applicant and the specified Manufacturer(s) will be bound to a Service Agreement for Follow-Up Services upon the earliest by any Subscriber of use of the prescribed UL Mark, acceptance of the factory inspection, or payment of the Follow-Up Service fees which will incorporate such GSA, this Follow-Up Service Procedure and the Follow-Up Service Terms which can be accessed by clicking here: <http://www.ul.com/contracts/Terms-After-12-31-2011>. In all other events, Follow-Up Services will be governed by and incorporate the terms of your applicable service agreement and this Follow-Up Service Procedure.

(106499-001) 584413 (Party Site)
ALTRA INDUSTRIAL MOTION (SHENZHEN) CO LTD
18 HUANZHEN RD
DABO INDUSTRIAL ZONE BOGANG VLG
SHAJING TOWN BAO'AN DIST
SHENZHEN
GUANGDONG 518104 CHINA

Factory ID: WS
UL Contracting Party for above site is: UL AG